



RAY International Electrical Contracting & Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

## INCIDENT NOTIFICATION

To be reported within 24 hours (maximum)

Abudhabi/ Dubai

### DISTRIBUTION TO:

MD, CEO, GMs, Discipline SR MGR, QHSE MGR & advisors, LINE Managers, HRA Manager

### REPORT ORIGINATED BY:

NAME:	Bhasker Reddy	COMPANY / DIVISION:	Project-244	GSM NO:	050 3363237
-------	---------------	---------------------	-------------	---------	-------------

LOCATION OF INCIDENT:	Khalifacity, basin southeast	DATE OF INCIDENT:	27-03-2023	TIME:	10:22 AM
-----------------------	------------------------------	-------------------	------------	-------	----------

INCIDENT TYPE: Other ADM fine

INCIDENT ACTUAL SEVERITY RATING: 2

POTENTIAL SEVERITY RATING: 3

RISK LEVEL: Moderate

#### Note:

Use the Risk Assessment Matrix to determine the **actual** and **potential** severity rating for the incident. Seek assistance from the HSE Advisor if required.

Incidents with a potential 'Medium or High Risk' shall be referred to the RAY QHSE Dept immediately

Low

Moderate

High

Likelihood \ Severity	Rare (1)	Unlikely (2)	Possible (3)	Likely (4)	Almost Certain (5)
Catastrophic (5)	Low	Moderate	High	High	High
Major (4)	Low	Moderate	Moderate	High	High
Moderate (3)	Low	Moderate	Moderate	Moderate	High
Minor (2)	Low	Moderate	Moderate	Moderate	Moderate
Negligible (1)	Low	Low	Low	Low	Low

### BRIEF DESCRIPTION OF INCIDENT

Identical interlock tiles were not used for reinstatement work after completion at PD rectification work. Due to this violation ADM inspector imposed fine of AED 500.

### BRIEF DESCRIPTION OF DAMAGE

Not applicable.

NUMBER OF PERSONS INJURED: 0

NAMES OF INJURED PEOPLE AND DETAILS OF INJURIES: Not Applicable.

### THE FOLLOWING FOR LOW POTENTIAL INCIDENTS-

(All incidents including Medium or High Potential **MUST** have a full investigation report completed)

IMMEDIATE CAUSES: Identical interlock tiles were not arranged before stating the reinstatement work.

UNDERLYING CAUSES: Work has not done as per ADM procedure.

### CORRECTIVE AND PREVENTIVE ACTIONS:

### RESPONSIBLE:

### CLOSED DATE:

Site Engineer make sure that Identical interlock tiles should be available at store before starting the work.

Employee-103

01.04.2023