

RAY International Electrical Contracting & Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

INCIDENT NOTIFICATION To be reported within 24 hours (maximum)

Abudhabi/ Dubai

DISTRIBUTIONTo: MD, CEO, GMs, Discipline SR MGR, QHSE MGR & advisors, LINE Managers, HRA Manager REPORT ORIGINATED BY: COMPANY / Fawad Zaman Proiect-353 GSM NO: 050 9771473 NAME: DIVISION: LOCATION OF DATE OF INCIDENT: Aweer 132 kV substation 04-07-2024 TIME: 08:59 INCIDENT: INCIDENT TYPE: **Near Miss** INCIDENT ACTUAL SEVERITY RATING: 3 Likelihood Almost Unlikely Possible Rare (1) Likely (4) Certain POTENTIAL SEVERITY RATING: 3 (2) (3) Severity (5) RISKLEVEL: Moderate Catastrophic (5) Lon Major (4) Low Moderate Moderate High High Use the Risk Assessment Matrix to determine the actual and potential severity rating for the incident. Seek assistance from the HSE Advisor if required. Moderate (3) Low Moderate Moderate Moderate High Moderate Incidents with a potential 'Medium or High Risk' shall be referred to the Minor (2) Low Moderate Moderate Moderate **RAY QHSE Dept immediately** Negligible (1) Low Low Low Low Moderate High BRIEF DESCRIPTION OF INCIDENT found hydraulic oil leakage at outriggers jacks hose in our 3 Ton HIAB 65761. BRIEF DESCRIPTION OF DAMAGE outrigger jacks not in good level. jacks bends towards front side and also their is leakage in hydrolic hose. 0 NUMBER OF PERSONS INJURED: nil NAMES OF INJURED PEOPLE AND DETAILS OF INJURIES THE FOLLOWING FOR LOW POTENTIAL INCIDENTS-(All incidents including Medium or High Potential MUST have a full investigation report completed) IMMEDIATE leakage in hydrolic hoses CAUSES UNDERLYING **CAUSES** need proper maintenance for the equipment. **CORRECTIVE AND PREVENTIVE ACTIONS:** RESPONSIBLE: CLOSED DATE: vehicle inspection and maintenance should be maintained for the vehicles. Employee-39 10/07/2024 Employee-8 bh vvgg