

## RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC

MOBILE CRANE CHECKLIST	Abu Dhabi/ Dubai
<b>Date:</b> 14-08-2023 <b>Location:</b> Dlh	Client: No Client
Project Code: SangProject1	Project Details: sang project(description)
Site In charge: sijina-test	Registration No.: h
Make & Model: a	Driving license 31-08-2023 Expiry:
Operator Name: h	Other Info: Test Info

OL N		СО	MPLIAN	ICE	REMARKS	ACTION TO BE TAKEN		
SI. No ITEMS	YES	NO	NA					
1	Is the crane safe working load suitable for the job? (The total load should not exceed more than 60% of crane capacity)	<b>~</b>						
2	Is crane third party certificate available?		✓					
3	Is operator third party certificate available?	<b>✓</b>						
4	Engine oil level		<b>✓</b>					
5	Engine coolant level	✓						
6	Hydraulic system oil level	<b>✓</b>						
7	Seat Belts	<b>✓</b>						
8	Condition of Battery and Lamps	<b>✓</b>						
9	Condition of wind screen & windows		<b>✓</b>					
10	Revolving lights in working condition.		<b>✓</b>					
11	Guards of moving and rotating parts	<b>✓</b>						

Ref No:	FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	1
---------	--------	-------------	----	-------------	------------	----------	---

	COMPLIANCE			REMARKS		ACTION TO BE TAKEN			
SI. No	ITEMS	YES	NO	NA NA	KEWIAKKS		ACTION TO BE TAKEN		
	Horn	1120							
	110111		<b>✓</b>						
12									
	Reverse Alarm	✓							
13									
	Air conditioner	<b>✓</b>							
14		*							
14									
	Tyre pressure & Tyre condition								
	Tyle pressure & Tyle condition		✓						
15									
	Hook and Hook Latch	<b>✓</b>							
16									
	Over-Hoist, Boom Limit								
	Switches working	✓							
17									
	Over load trip.	✓							
18									
	Boom Angle indicator								
40			✓						
19									
	Safe Working Load indicator								
	Sale Working Load Indicator		✓						
20									
	Boom Brake & Lock	✓							
21									
	Main clutch	,							
		✓							
22									
	Deterioration on local and in								
	Deterioration or leakage in lines, tanks, hoses, valves,		✓						
23	pumps, cylinders and other								
	parts of air or hydraulic system								
	Fire Extinguisher in operator	,							
0.4	cabin	✓							
24									
	Load short provided	1	-						
	Load chart provided		✓						
25									
	Operator manual in crane		<b>√</b>						
26			'						
20									
	Lattice boom lowered to					-			
	ground and fully inspected	✓							
27	, , , , , , , , , , , , , , , , , , , ,								
	Condition of the slings	✓							
28									
<u> </u>	I	1	I	<u> </u>	<u> </u>	<u> </u>			
Ref No:	FR-604 <b>Version. No</b>		)1	Issued	Date 08.09.2	016	Page No:	2	
<u> </u>	L						ı		

SI. No ITEMS	ITEMO	СО	MPLIAN	CE	REMARKS	ACTION TO BE TAKEN
		YES	NO	NA		
	Soil Condition	<b>√</b>				
29						
	Safe distance from edge of					
30	excavation	<b>✓</b>				
30						
	Out riggers fully extended					
	Out riggers raily externaed	✓				
31						
	Outrigger pads in good condition	✓				
32	Condition					
	Stability of crane	✓				
33						
	Wheel chokes available	<b>√</b>				
34		'				
0.						
	Anemometer in working					
25	condition.	<b>✓</b>				
35						
	Overhead And Below Ground,					
	Minimum Limit Approach	✓				
36	Regulation At All Times					
	Safe Distance From Respective Equipment And	✓				
37	Lines					
General Co	gbb					
Inspected	By: Sijina			Site	I/C: sijina-test	

Inspected By :	Sijina	Site I/C :	sijina-test
Sign/Date :			
RAY No :	RU/603	RAY No :	RU/603

Signature:

Ref No:	FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	3	
---------	--------	-------------	----	-------------	------------	----------	---	--