

RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC

QHSE SITE INS	SPECTION CH		Abu Dhabi/ Dubai			
Date : 20-06-2023	Location: gf			Client: abu dhabi		
Project Code: ABU DHABI-COM-S	RESOURCE	Project Details:	ABU DHA	BI-COM-RESOURCES		
Activity g		Site Incharge:	Hind Yaich	Achour		

	Task Description			LIANCE		
SI. No	Task Bescription	YES NO NA			REMARKS	
	HSE					
	Check that PTW/ NOC's available at site.					
12			✓			
	Check if any Internal Permits issued and validi	tv				
13	ensured.	•		✓		
	Ensure that electrical safety rules and procedu	re are				
14	followed.			✓		
	Check the availability of Job HSE plan and Ris	k				
15	Assessment Matrix for the activity.			✓		
	Check that the toolbox talk is conducted before	e starting	√			
16	the activity and recorded.		*			
	Ensure that work is being carried out on the co	orrect	√			
17	piece of Equipment/OHL.		*			
	Check the condition of tools & tackles.			√		
18				v		
	Check color code in Power tools, lifting tools a	nd		√		
19	tackles.			·		
	Check the availability of first aid boxes with ch	ecklist	√			
20	duly filled and signed.					
	Check the availability of First aider and Fire wa	arden.	√			
21						
	Check the condition of Fire extinguisher, calibr			✓		
22	valid, availability of monthly inspection sticker.					
20	Check good level of Housekeeping maintained	l at site.			√	
23						
0.4	Waste disposed from site appropriately.				✓	
24						
25	Check the storage of material appropriate at si	te.			✓	
25						
26	Check all workforce is site with appropriate PPE and using it.			✓		
۷۵		1.0				
27	Check in random the condition of PPE for condition, clean and hygienic			✓		
۷1						
28	Check the machinery/ equipment having 3rd p certificate and operator certified.	arty		✓		
	·					
29	STOP card/ Near Miss report records available	;		✓		
	1		<u> </u>			
No:	FR-426 Version. No 04	Issued [Date :	20.	06.2023	Page No:

SI. No	Task Description			PLIANCE		DEMARKS	
31. NO		•	YES	NO	NA	REMARKS	
30	Check Labour welfare facilities are at site like umbrella/ tent, drinking water facilities etc. are available.				✓		
31	Check sufficient barricading facilities are available with RAY Logo in it.			✓			
32	Check too placed at	ols mat is available at site and all tools are tool mat.		✓			
33		andatory sign boards like project sign board, ork, unauthorized entry, etc. are displayed at			√		
34		ifficient lighting arrangement and warning available at site.		✓			
35	dfeawed			✓			
1	tester ed	lit	√				
		Quality		•		·	
1	Check the availability of controlled copy of method statement.						
2	Check whether the team is aware of the work methodology and Risk assessment.						
3	Check that measuring/ Testing equipment have valid calibration certificate & calibration sticker.						
4	Check that sufficient tools and materials are available to carry out the job.						
5	Check that proper tools and materials are used to carry out the job.						
6	Check whether proper planning has been done for the activity.						
7	Check that sufficient manpower available to carry out the activity.						
8	Check whether plan for Tomorrow/Next week/ Next month available		√				
9	Check whether mandatory site documents are available at site.		√				
10	Check vehicle log sheet is entered properly and signed by supervisors.		✓				
Check labour timecard is filled on daily basis with supervisor signature.			✓				
Comments	et						
Inspected By(RAY)				Reviewed By (RAY)			
Name		123treesaSang		K.Rajkumar			
Designation	1	TestDesgntion		TestDesgntion			
Signature&l	Date						

Ref No: FR-426 Version. No	04	Issued Date :	20.06.2023	Page No:	2
----------------------------	----	---------------	------------	----------	---