

RAY International Electrical Contracting & Maintenance LLC **RAY International Electrical Contracting LLC**

INTERNATIO	RAY In	<u>iternational</u>	Power LLC							
	TO	OL BOX TA	LKS				Abu	Dhabi/ Dubai		
Project Nan			Life Saving Rules: Tick on the boxes which you being discuss during TBT			Tick on the boxes which required your plan for the job				
@newte	est		Don't walk under a		<u>a</u>			ryone have correct PPE?		
Location:			suspended load				Do you ha	ave all required tools, are		
dlh			Don't smoke outsid				they corre	ect & they are in good		
Client:			designed smoking	areas			condition?	? ne aware of themselves and	$\overline{\mathbf{V}}$	
Supervisor Date:	12-10-2023		Conduct gas test required	when	Ø		others act	tivities happening on-site? discussed Life Saving		
No.of manp	ower:	5	Work with a valid v				Have you	agreed how to		
Time:	10:49		permit when requir					cate with each other? ryone know that if there is a		
Job type:	f		No drugs or alcoho working or driving	ol while			shift change then another TBT is required?			
Lab Bassintian				While driving don't use the			Does appropriate posters and sign boards kept at site			
Job Description:			mobile phone and exceed speed limit				Are using tools being inspected &			
g			Obtain permit for w	vorking in	V			updated?		
			confined Space				function?	cy switches properly		
			Verify isolation bef		Ø		Good hou	sekeeping?		
Tools and E	Equipment used	:	begins and use the specified life prote				Proper ba	rricading?	$\overline{\checkmark}$	
g			Wear your seat be	lt	Ø		Check if is implemen	solation required and t.		
Job Start:	10:47:00		Obtain authorization	on before			Check job	requirements & timings		
End Time:	10:47:00		overriding					are of the emergency		
Conducted	-		Follow prescribed	journey	Ø		response. Check if p	ermit to work is required		
sijin								ds identified &controls		
Ray No. :	RU/603		Protect yourself ag		V		inplace.			
Signature:			fall when working a	fall when working at height			Does the sufficient number of supervisors present for the crews			
	Use hazard	s warning sig	ns as remainders	and tick t	the s	signs be		ussed during TBT		
Flammable	Lifting in progress	Equipment/ve hicles	Falling Slippery objects □	Toxic		Electri hazaro	l pro	essure hazard linders		
		H	IAZARD CO	NTROI	.5	HFF	Т		\neg	
	Task		Hazards			ontrols		Responsibilities	\neg	
0123456 1234567 0123456 1234567 0123456 1234567 0123456	890123456789 78901 890123456789 78901 890123456789	hhb		hh				999		

ATTENDANCE SHEET											
S.No	Emp.No.	Name	Company	Designation	Signature						

01 08.09.2016 Ref No: FR-646 Page 1 of 1 Version. No Issued Date: