

5678901234567890123 4567890123456789012 3456789012345678901

RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC

RAY International Power LLC

TOOL BOX TALKS							Abu Dhabi/ Dubai		
Project Nar		OL DOX IA	Life Saving Rules: Tick on the boxes			Tick on the boxes which required			
SangNew			which you being discuss during TBT			your plan for the job			
Location:			Don't walk under a suspended load			Does eve	ryone ha	ve correct PPE?	
						-		quired tools, are	$\overline{\checkmark}$
Dlh			Don't smoke outside			they corre		are in good	
Client:			designed smoking ar	eas				e of themselves and	$\overline{\mathbf{A}}$
Supervisor	,		Conduct gas test wh	ien 🔽		others ac	tivities ha	ppening on-site?	Ľ
Date:	04-10-2023		required			-	discusse	ed Life Saving	$\overline{\mathbf{Q}}$
No of many		4	Work with a valid wor	rk 🔲		Rules? Have you	agreed h	now to	
			permit when required			communicate with each other?			V
Time: 10:49			No drugs or alcohol while working or driving						
Job type: a									
			While driving don't us	se the 🖂		•		posters and sign	\square
Job Descri	ption:		mobile phone and exceed			boards kept at site			
а			speed limit				Are using tools being inspected & calibration updated?		$\overline{\mathbf{Q}}$
			Obtain permit for wor confined Space	Obtain permit for working in		Emergency switches properly		$\overline{\mathbf{A}}$	
			·			function?	-		۳
			Verify isolation before	e work		Good hou	ısekeepir	ng?	$\overline{\mathbf{A}}$
Tools and Equipment used:			begins and use the specified life protection			Proper barricading?		$\overline{\mathbf{A}}$	
а			Wear your seat belt			Check if isolation required and			
	10.47.00					implemen			
Job Start: 10:47:00			Obtain authorization before overriding			Check job requirements & timings Team aware of the emergency			$\overline{\mathbf{Q}}$
End Time: 10:47:00									
Conducted By:			Follow prescribed journey			response. Check if permit to work is required			
sijir	na-test		i olioni procenized jee	e,				•	\square
Ray No. : RU/603			Dretect yourself against a			Job hazards identified &controls inplace.			
Signature:			Protect yourself against a fall when working at height			Does the sufficient number of			$\overline{\Delta}$
orginataro.						supervisors present for the crews			
	Use hazard	ls warning sig	ns as remainders a	and tick the	signs bei	ng disc	ussed o	during TBT	
Flammable	Lifting in progress	•	alling Slippery	Toxic	Electruc hazard		gh essure	Entaglement hazard	
_	_	hicles	_	_	_	-	linders	_	
		<u>H</u>	<u>AZARD CON</u>				•		
Task			Hazards Conti		ontrols			Responsibilities	
1234567890123456789 hh			hhg				gg		
	789012345678			<u> </u>					
	678901234567 567890123456								
	3456789012345								
6789012	3/567800123/								

2345678901											
	ATTENDANCE SHEET										
S.No	Emp.No.	Name	Company	Designation	Signature						
	2,603	sijina-test	Company1								

Ref No: FR-646 **Version. No** 01 **Issued Date:** 08.09.2016 **Page 1 of 1**