

RAY International Electrical Contracting & Maintenance LLC **RAY International Electrical Contracting LLC**

INTERIORIE	RAY In	<u>iternational</u>	Power LLC						
	TO	OL BOX TA	LKS			Abu	Dhabi/ Dubai		
Project Nar			Life Saving Rules: Tick on the boxes which you being discuss during TBT				Tick on the boxes which required your plan for the job		
@newte	est		Don't walk under a		<u>, 121</u>	_	ryone have correct PPE?		
Location:			suspended load	_		Do you ha	ave all required tools, are		
dlh			Don't smoke outsid	L		they corre	ect & they are in good		
Client:			designed smoking a	areas		condition	? one aware of themselves and	V	
Supervisor Date:	12-10-2023		Conduct gas test w required	/hen [<u> </u>	others ac	tivities happening on-site? discussed Life Saving		
No.of manp	power:	5	Work with a valid w	L		Have you	agreed how to		
Time: 10:49			permit when require	·		communicate with each other? Does everyone know that if there is a			
Job type:	f		No drugs or alcohol working or driving	l while [☑		ige then another TBT is		
Job Descri	ption:			While driving don't use the mobile phone and exceed			Does appropriate posters and sign boards kept at site		
g			speed limit			Are using tools being inspected & calibration updated?			
			Obtain permit for wo	orking in [☑		cy switches properly		
			Verify isolation befo		<u> </u>		usekeeping?		
Tools and Equipment used:			begins and use the specified life protection		Proper ba	Proper barricading?			
g			Wear your seat belt		<u> </u>	Check if i	solation required and nt.	<u>a</u>	
Job Start:	10:47:00		Obtain authorization	n before I	<u>√</u>	Check job	requirements & timings		
End Time:	10:47:00		overriding		<u> </u>		are of the emergency		
Conducted	-		Follow prescribed jo	 ourney [▼	response Check if p	permit to work is required		
sijir							rds identified &controls		
Ray No. : RU/603				Protect yourself against a		inplace.	inplace.		
Signature:		fall when working a	fall when working at height		Does the sufficient number of supervisors present for the crews				
	Use hazard	s warning sig	ு gns as remainders	and tick th	ne signs				
Flammable	Lifting in progress	Equipment/ve hicles	Falling Slippery objects	Toxic □	Ele haz □	ard pr	gh Entaglement essure hazard ≀linders		
		H	IAZARD CO	NTROI	SHF	FT			
	Task	-	Hazards		Controls		Responsibilities		
0123456 1234567 0123456 1234567 0123456 1234567 0123456	7890123456789 67890 7890123456789 67890 7890123456789 67890 7890123456889	hhb		hh			999		

ATTENDANCE SHEET										
S.No	Emp.No.	Name	Company	Designation	Signature					

01 08.09.2016 Ref No: FR-646 Page 1 of 1 Version. No Issued Date: