

# REPORT

## OF THOROUGH EXAMINATION

### CHAIN SLING



Issued By:



Date of Issue: 18-07-2025

ReportNo.: **DRAFT**

ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe!

This equipment certificate complies with the requirements of Emirates International Accreditation Centre for inspection bodies working in the field of Lifting Equipment and Lifting Accessories (EIAC-RQ-IB-002), reference standard BS EN 818-1:1996+A1:2008, BS EN 818-2: 1996 +A1:2008, BS EN 818-3: 1999 +A1:2008, BS EN 818-4:1996+A1:2008, BS EN 818-5:1999+A1:2008, BS EN 818-6:2000+A1:2008, BS EN 818-7:2002+A1:2008, and Manufacturer's Specification

Owner Name: Mr Dhillon, Mr. Mani  
Office Address: P.O. Box: 11072  
Dubai  
United Arab Emirates  
Equipment Location: Gold 2 Project

#### INSPECTION DETAILS

|                             |               |                            |               |
|-----------------------------|---------------|----------------------------|---------------|
| Date of Inspection:         | 18-07-2025    | Expiry Date:               | <b>FAILED</b> |
| Inspection Type:            | PERIODIC      |                            |               |
| Previous Inspection Report: | cb            | Last Proof Load Test:      | 18-07-2025    |
| Test Method                 | <b>CSI-07</b> | Calibrated Test Equipment: | r             |
|                             |               | Client Test Equipment:     | f             |

#### EQUIPMENT INSPECTION

| EQUIPMENT ID & SERIAL NO.: | EQUIPMENT DESCRIPTION                                                                    | QTY | SAFE WORKING LOAD | TEST LOAD APPLIED | TYPE OF TEST & RESULT |
|----------------------------|------------------------------------------------------------------------------------------|-----|-------------------|-------------------|-----------------------|
| r                          | Manufacturer: t<br>Chain Diameter: g<br>Chain Length: f<br>Number of Legs: g<br>Grade: g | t   | t                 | t                 | g                     |

This is to certify that the above item/s described in this certificate was tested and particulars are correct.

CSSC has inventoried, inspected, verified and tested above mentioned equipment in accordance with the reference standards cited herein and consistent with CSSC policies and procedure. We certify this above mentioned equipment is **UNSAFE TO USE**, condition prevails at the time of this inspection.

All the information obtained /gathered during the inspection shall be preserved as confidential.

This inspection has been carried out as per local order no. : 2/2010;

This inspection certificate / report shall not be reproduced except in full without the approval of Claymore and the Client.

Inspected By: Maricris Barro Elcano

Name & Signature of Inspector

# REPORT OF THOROUGH EXAMINATION CHAIN SLING

ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe ThinkSafe! ThinkSafe!

| EXAMINATION REPORT    |                                                                                                                                                              |                          |                          |                                     |                          |         |
|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|--------------------------|-------------------------------------|--------------------------|---------|
| EQUIPMENT PARTS       |                                                                                                                                                              | S                        | NS                       | NA                                  | SE                       | REMARKS |
| Document verification |                                                                                                                                                              |                          |                          |                                     |                          |         |
| 1.                    | Previous inspection report                                                                                                                                   | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 2.                    | Manufacturer technical specification / conformity report                                                                                                     | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| Component             |                                                                                                                                                              |                          |                          |                                     |                          |         |
| 3.                    | Marking of SWL @ angle and ID No.                                                                                                                            | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 4.                    | Chain sling condition<br>(wear: 8% ; elongation due to wear: 5% ;<br>elongation due to stretch: 0%)(pitch: 3xdia)                                            | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 5.                    | Erosion or corrosion condition                                                                                                                               | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 6.                    | General structure (bend, twist, stretch, Cuts,<br>nicks, gouges, cracks, excessive corrosion,<br>heat discolorations, or any other defects in<br>chain etc.) | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 7.                    | Welding joint                                                                                                                                                | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| Fittings              |                                                                                                                                                              |                          |                          |                                     |                          |         |
| 8.                    | Master link                                                                                                                                                  | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 9.                    | Sub link                                                                                                                                                     | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 10.                   | Coupling                                                                                                                                                     | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 11.                   | Clutches                                                                                                                                                     | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 12.                   | All components are same grade                                                                                                                                | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 13.                   | Hook condition<br>(wear: 10% ; throat opening:15% ; twist: 10°)                                                                                              | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |
| 14.                   | Safety Latch                                                                                                                                                 | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |         |

S-Satisfactory, NS-Not Satisfactory, NA-Not Applicable, SE-Serviceable • Finding • Critical Finding

|                         |                         |                |
|-------------------------|-------------------------|----------------|
| Finding:                | Critical Finding:       | Other Remarks: |
| Target Date of Closure: | Target Date of Closure: |                |

## PHOTOS OF INSPECTED CHAIN SLING