

REPORT

OF THOROUGH EXAMINATION

CHAIN SLING



Issued By:



Date of Issue: 13-11-2025

ReportNo.: **DRAFT**

ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe!

This equipment certificate complies with the requirements of Emirates International Accreditation Centre for inspection bodies working in the field of Lifting Equipment and Lifting Accessories (EIAC-RQ-IB-002), reference standard BS EN 818-1:1996+A1:2008, BS EN 818-2: 1996 +A1:2008, BS EN 818-3: 1999 +A1:2008, BS EN 818-4:1996+A1:2008, BS EN 818-5:1999+A1:2008, BS EN 818-6:2000+A1:2008, BS EN 818-7:2002+A1:2008, and Manufacturer's Specification

Owner Name: Nandan Narayanan
Office Address: P.O.Box:8778,
SAIF Zone, Sharjah
U.A.E.,
Equipment Location: SAIF Zone, SHJ

INSPECTION DETAILS

Date of Inspection:	13-11-2025	Expiry Date:	FAILED
Inspection Type:	THOROUGH		
Previous Inspection Report:	ch	Last Proof Load Test:	13-11-2025
Test Method	CSI-07	Calibrated Test Equipment:	gy
		Client Test Equipment:	hu

EQUIPMENT INSPECTION

EQUIPMENT ID & SERIAL NO.:	EQUIPMENT DESCRIPTION	QTY	SAFE WORKING LOAD	TEST LOAD APPLIED	TYPE OF TEST & RESULT
hu	Manufacturer: gh Chain Diameter: gy Chain Length: hu Number of Legs: g Grade: h	gu	gu	yu	gy

This is to certify that the above item/s described in this certificate was tested and particulars are correct.

CSSC has inventoried, inspected, verified and tested above mentioned equipment in accordance with the reference standards cited herein and consistent with CSSC policies and procedure. We certify this above mentioned equipment is **UNSAFE TO USE**, condition prevails at the time of this inspection.

All the information obtained /gathered during the inspection shall be preserved as confidential.

This inspection has been carried out as per local order no. : 2/2010;

This inspection certificate / report shall not be reproduced except in full without the approval of Claymore and the Client.

Inspected By: Katrina



Name & Signature of Inspector

REPORT OF THOROUGH EXAMINATION CHAIN SLING

ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe ThinkSafe! ThinkSafe!

EXAMINATION REPORT						
EQUIPMENT PARTS		S	NS	NA	SE	REMARKS
Document verification						
1.	Previous inspection report	☒	☐	☐	☐	
2.	Manufacturer technical specification / conformity report	☒	☐	☐	☐	
Component						
3.	Marking of SWL @ angle and ID No.	☒	☐	☐	☐	
4.	Chain sling condition (wear: 8% ; elongation due to wear: 5% ; elongation due to stretch: 0%)(pitch: 3xdia)	☒	☐	☐	☐	
5.	Erosion or corrosion condition	☒	☐	☐	☐	
6.	General structure (bend, twist, stretch, Cuts, nicks, gouges, cracks, excessive corrosion, heat discolorations, or any other defects in chain etc.)	☒	☐	☐	☐	
7.	Welding joint	☒	☐	☐	☐	
Fittings						
8.	Master link	☒	☐	☐	☐	
9.	Sub link	☒	☐	☐	☐	
10.	Coupling	☒	☐	☐	☐	
11.	Clutches	☒	☐	☐	☐	
12.	All components are same grade	☒	☐	☐	☐	
13.	Hook condition (wear: 10% ; throat opening:15% ; twist: 10°)	☒	☐	☐	☐	
14.	Safety Latch	☒	☐	☐	☐	

S-Satisfactory, NS-Not Satisfactory, NA-Not Applicable, SE-Serviceable • Finding • Critical Finding

Finding: gj	Critical Finding: hj	Other Remarks:
Target Date of Closure: 19-11-2025	Target Date of Closure: 28-11-2025	

PHOTOS OF INSPECTED CHAIN SLING