

REPORT OF THOROUGH EXAMINATION EYEBOLT



Issued By:



Date of Issue: 11-04-2025

ReportNo.: **DRAFT**

ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe! ThinkSafe!

This equipment certificate complies with the requirements of Emirates International Accreditation Centre for inspection bodies working in the field of Lifting Equipment and Lifting Accessories (EIAC-RQ-IB-002), reference standard BS EN ISO 3266:2010+A1:2015 and Manufacturer's Specification.

Owner Name: Sukesh M.Y- Project Manager 050 4576747
Office Address: P.O.Box 24755
Dubai,
United Arab Emirates
Equipment Location: DMC

INSPECTION DETAILS					
Date of Inspection:	11-04-2025	Expiry Date:	FAILED		
Inspection Type:	THOROUGH				
Previous Inspection Report:	f	Last Proof Load Test:	11-04-2025		
Test Method	CSI-08	Calibrated Test Equipment:	f		
		Client Test Equipment:	f		
EQUIPMENT INFORMATION					
EQUIPMENT ID & SERIAL NO.:	EQUIPMENT DESCRIPTION	QTY	SAFE WORKING LOAD	TEST LOAD APPLIED	TYPE OF TEST & RESULT
f	Manufacturer: s Thread diameter: 4 Grade: s	1	4	4	e
1. Is this the first examination after installation or assembly at a new location? ☒ Yes ☐ No					
2. If the answer to the above question is Yes, then has the equipment been installed correctly? ☒ Yes ☐ No					
3. Was the inspection carried out in accordance out in accordance with an examination scheme? ☒ Yes ☐ No					

This is to certify that the above item/s described in this certificate was tested and particulars are correct.

CSSC has inventoried, inspected, verified and tested above mentioned equipment in accordance with the reference standards cited herein and consistent with CSSC policies and procedure. We certify this above mentioned equipment is **UNSAFE TO USE**, condition prevails at the time of this inspection.

All the information obtained /gathered during the inspection shall be preserved as confidential.

This inspection has been carried out as per local order no. : 2/2010;

This inspection certificate / report shall not be reproduced except in full without the approval of Claymore and the Client.

Inspected By: Wazeem Ibrahim

Name & Signature of Inspector

Claymore Security and Safety Consultants, P.O. Box 23420 Dubai & Abu Dhabi, U.A.E., Tel. No.: 04 884 8446,

E-mail: claysafe@claycss.ae, Website: www.claymoresafe.ae

REPORT OF THOROUGH EXAMINATION EYEBOLT



Issued By:



Date of Issue: 11-04-2025

ReportNo.: **DRAFT**

ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe ThinkSafe! ThinkSafe!

EXAMINATION REPORT						
EQUIPMENT PARTS		S	NS	NA	SE	REMARKS
Document verification						
1.	Previous inspection report	☐	☐	☒	☐	
2.	Manufacturer technical specification / conformity report	☐	☐	☒	☐	
	Component	☐	☐	☒	☐	
3.	Marking of CE, SWL and ID No.	☐	☐	☒	☐	
4.	Erosion or corrosion condition	☐	☐	☒	☐	
5.	Eye bolt condition	☐	☐	☒	☐	
6.	General structure (bend, twist, stretch, Cuts, nicks, gouges, cracks, excessive corrosion, heat discolorations, or any other defects in chain etc.)	☐	☐	☒	☐	
7.	Eye bolt thread condition	☐	☐	☒	☐	

S-Satisfactory, NS-Not Satisfactory, NA-Not Applicable, SE-Serviceable ♦ Finding ● Critical Finding

Finding: c	Critical Finding: x	Other Remarks: v
Target Date of Closure:	Target Date of Closure:	

PHOTOS OF INSPECTED EYE BOLT