## REPORT

## OF THOROUGH EXAMINATION **EYEBOLT**





Date of Issue: 11-04-2025 ReportNo.:DRAFT

ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe!

This equipment certificate complies with the requirements of Emirates International Accreditation Centre for inspection bodies working in the field of Lifting Equipment and Lifting Accessories (EIAC-RQ-IB-002), reference standard BS EN ISO 3266:2010+A1:2015 and Manufacturer's Specification.

Owner Name: Sukesh M.Y- Project Manager 050 4576747

Office Address: P.O.Box 24755

Dubai,

United Arab Emirates Equipment Location: DMC

	INSPECTION	DETAILS					
Date of Inspection:	11-04-2025	Expiry Date:			FAILED		
Inspection Type:	THOROUGH	•		•			
Previous Inspection Report:	f	Last Proof L	oad Test:	11-04-2025			
Test Method	CSI-08	Calibrated 7 Equipment: Client Test		f			
	EQUIPMENT INI			'			
EQUIPMENT ID & SERIAL NO.:	EQUIPMENT DESCRIPTION	QTY			TEST LOAD APPLIED	TYPE OF TEST & RESULT	
f	Manufacturer: s Thread diameter: 4 Grade: s	1	4		4	е	
2. If the answer to the a	nation after installation or assemb above question is Yes, then has th carried out in accordance out in ac	e equipment	been installe	ed cor	rectly?	es 🗆 No	

This is to certify that the above item/s described in this certificate was tested and particulars are correct.

CSSC has inventoried, inspected, verified and tested above mentioned equipment in accordance with the reference standards cited herein and consistent with CSSC policies and procedure. We certify this above mentioned equipment is **UNSAFE TO USE**, condition prevails at the time of this inspection.

All the information obtained /gathered during the inspection shall be preserved as confidential.

This inspection has been carried out as per local order no.: 2/2010;

This inspection certificate / report shall not be reproduced except in full without the approval of Claymore and the Client.

Inspected By: Wazeem Ibrahim

Name & Signature of Inspector

Page1

## REPORT

## OF THOROUGH EXAMINATION **EYEBOLT**





ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe!

**Date of Issue**: 11-04-2025 ReportNo.:DRAFT

EQUIPMENT PARTS		S	NS	NA	SE	REMARKS
	Docur	nent v	erifica	tion		
. 7	Previous inspection report		M.	<b>Ø</b>		(C)
2.	Manufacturer technical specification / conformity report			Ø		
	Component			<b>Ø</b>		
3.	Marking of CE, SWL and ID No.			Ø		-
1.	Erosion or corrosion condition					JORE OF
5.	Eye bolt condition		115	Ø		NO.
6.	General structure (bend, twist, stretch, Cuts, nicks, gouges, cracks, excessive corrosion, heat discolorations, or any other defects in chain etc.)		7	Ø		Cry Cry
7.	Eye bolt thread condition					-6

Finding:	Critical Finding:	Other Remarks:
С	x	v CL
sales sales	the state of the s	
Target Date of Closure:	Target Date of Closure:	

PHOTOS OF INSPECTED EYE BOLT