

REPORT

OF THOROUGH EXAMINATION

LIFTING FRAME

This equipment certificate complies with the requirements of Emirates International Accreditation Centre for inspection bodies working in the field of Lifting Equipment and Lifting Accessories (EIAC-RQ-IB-002), reference standard BS EN 13155:2020, LEEA, LOLER, and Manufacturer's Specification.

Owner Name: Mr. Raj
Office Address: P.O.Box: 31286
Dubai,
United Arab Emirates.
Equipment Location: NA

INSPECTION DETAILS				
Date of Inspection:	18-07-2025	Expiry Date:	FAILED	
Inspection Type:	PERIODIC			
Previous Inspection Report:	12345	Last Proof Load Test:	18-07-2025	
Test Method	123456	Calibrated Test Equipment:	12345	
		Client Test Equipment:	fg	
EQUIPMENT INSPECTION				
Equipment Description:	t			
ID & Serial No.:	y	Overall Dimensions:	L:c(m)	W:f(m)
Equipment Type:	☐ Lifting Beam ☒ Spreader Beam ☐ Lifting Frame		H:c(m)	Th:g(m)
		No. of Pad Eyes / Legs:	t	
		Pad Eye Hole Diameter:	t	
Equipment Manufacturer:	f	Pad Eye Thickness:	f	
Manufacture Year:	18-07-2025	Safe Working Load:	b	
		Test Load Applied:	g	
1. Is this the first examination after installation or assembly at a new location?			☒ Yes	☐ No
2. If the answer to the above question is Yes, then has the equipment been installed correctly?			☐ Yes	☒ No
3. Was the inspection carried out in accordance with an examination scheme?			☐ Yes	☒ No

This is to certify that the above item/s described in this certificate was tested and particulars are correct.

CSSC has inventoried, inspected, verified and tested above mentioned equipment in accordance with the reference standards cited herein and consistent with CSSC policies and procedure. We certify this above mentioned equipment is **UNSAFE TO USE**, condition prevails at the time of this inspection.

All the information obtained /gathered during the inspection shall be preserved as confidential.

This inspection has been carried out as per local order no. : 2/2010;

This inspection certificate / report shall not be reproduced except in full without the approval of Claymore and the Client.

Inspected By: Katrina

happy

Name & Signature of Inspector

REPORT

OF THOROUGH EXAMINATION

LIFTING FRAME

EXAMINATION REPORT						
EQUIPMENT PARTS		S	NS	NA	SE	REMARKS
Document Verification						
1.	Previous inspection report	☐	☐	☒	☐	
2.	Maintenance log sheet	☐	☐	☒	☐	
3.	Mfg. Manual & technical instruction	☐	☐	☒	☐	
Mechanical Structure						
4.	Marking / hard stamping of SWL and MGW	☐	☐	☒	☐	
5.	Pad eye assembly on lifting structure	☐	☐	☒	☐	
6.	Welding condition on lifting structure	☐	☐	☒	☐	
7.	Bolts, hinges, rubber sealing are secured	☐	☐	☒	☐	
8.	Pad eye hole (smooth & efficient, no wear, undue elongation or physical damage)	☐	☐	☒	☐	
9.	General structure(Condition for deformation, Distortion, cracks or damage)	☐	☐	☒	☐	
10.	Pitting or general corrosion underneath	☐	☐	☒	☐	
11.	Supporting members	☐	☐	☒	☐	
12.	General painting status	☐	☐	☒	☐	
13.	Check of associated sling assembly if any	☐	☐	☒	☐	
14.	Warning sign	☐	☐	☒	☐	
Load Testing						
15.	Load test (as per the Mfg./LOLER) - SWL up to 10ton: PL = SWL x 2 10ton up to 160ton: PL = (1.04xSWL+9.6ton) - Over 160ton: PL = SWL x 1.1	☐	☐	☒	☐	

S-Satisfactory, NS-Not Satisfactory, NA-Not Applicable, SE-Serviceable • Finding • Critical Finding

Finding: fy	Critical Finding:	Other Remarks:
Target Date of Closure:	Target Date of Closure:	

REPORT OF THOROUGH EXAMINATION LIFTING FRAME



Issued By:



Date of Issue: 18-07-2025

ReportNo.: **DRAFT**

ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe ThinkSafe! ThinkSafe!

PHOTOS OF INSPECTED LIFTING FRAME