

REPORT

OF THOROUGH EXAMINATION

LIFTING FRAME



Issued By:



Date of Issue: 21-04-2025

ReportNo.: **JO-10451/1**

ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe!

This equipment certificate complies with the requirements of Emirates International Accreditation Centre for inspection bodies working in the field of Lifting Equipment and Lifting Accessories (EIAC-RQ-IB-002), reference standard BS EN 13155:2020, LEEA, LOLER, and Manufacturer's Specification.

Owner Name: Hardy Yu Roleda 050-4966269
Office Address: Plot No M00401, Unilever House Dubai,
P.O. Box 17055
Jebel Ali ,Dubai ,United Arab Emirates
Equipment Location:

INSPECTION DETAILS				
Date of Inspection:	21-04-2025	Expiry Date:	21-04-2025	
Inspection Type:	PERIODIC			
Previous Inspection Report:	bnx	Last Proof Load Test:	21-04-2025	
Test Method	CSI-16	Calibrated Test Equipment:	jsu	
		Client Test Equipment:	vzg	
EQUIPMENT INSPECTION				
Equipment Description:	jf			
ID & Serial No.:	bdb	Overall Dimensions:	L:9(m)	W:7(m)
Equipment Type:	☐ Lifting Beam ☐ Spreader Beam ☒ Lifting Frame		H:8(m)	Th:5(m)
		No. of Pad Eyes / Legs:	6	
		Pad Eye Hole Diameter:	4	
Equipment Manufacturer:	hd	Pad Eye Thickness:	1	
Manufacture Year:	21-04-2025	Safe Working Load:	2	
		Test Load Applied:	3	
1. Is this the first examination after installation or assembly at a new location?			☒ Yes	☐ No
2. If the answer to the above question is Yes, then has the equipment been installed correctly?			☒ Yes	☐ No
3. Was the inspection carried out in accordance with an examination scheme?			☐ Yes	☒ No
The owner shall perform the next inspection no later than 1 Months From the date of issue.				

This is to certify that the above item/s described in this certificate was tested and particulars are correct.

CSSC has inventoried, inspected, verified and tested above mentioned equipment in accordance with the reference standards cited herein and consistent with CSSC policies and procedure. We certify this above mentioned equipment is **SAFE TO USE**, condition prevails at the time of this inspection, safe to use further with qualified operator. That the owner or his designated agent or contractor, hereafter owner, continues to perform maintenance in accordance with the original equipment manufacturer's preventive maintenance guideline and procedures and makes no unauthorized changes to the equipment's controls and mechanisms. CSSC makes no claims regarding the condition or safety of the equipment after we have completed this inspection and departed the property. CSSC disclaims any warranty of any kind either expressed or implied including without limitation warranties of merchantability or fitness for a particular purpose. This certificate becomes invalid in the event of any repair or alterations are done, in which case it must be retested.

All the information obtained /gathered during the inspection shall be preserved as confidential.

This inspection has been carried out as per local order no. : 2/2010;

This inspection certificate / report shall not be reproduced except in full without the approval of Claymore and the Client.

Inspected By: Katrina

Name & Signature of Inspector

Claymore Security and Safety Consultants, P.O. Box 23420 Dubai & Abu Dhabi, U.A.E., Tel. No.: 04 884 8446,

E-mail: claysafe@claycss.ae, Website: www.claymoresafe.ae

REPORT

OF THOROUGH EXAMINATION

LIFTING FRAME

EXAMINATION REPORT					
EQUIPMENT PARTS		S	NS	NA	SE
Document Verification					
1.	Previous inspection report	☐	☒	☐	☐
2.	Maintenance log sheet	☐	☒	☐	☐
3.	Mfg. Manual & technical instruction	☐	☒	☐	☐
Mechanical Structure					
4.	Marking / hard stamping of SWL and MGW	☐	☒	☐	☐
5.	Pad eye assembly on lifting structure	☐	☒	☐	☐
6.	Welding condition on lifting structure	☐	☒	☐	☐
7.	Bolts, hinges, rubber sealing are secured	☐	☒	☐	☐
8.	Pad eye hole (smooth & efficient, no wear, undue elongation or physical damage)	☐	☒	☐	☐
9.	General structure (Condition for deformation, Distortion, cracks or damage)	☐	☒	☐	☐
10.	Pitting or general corrosion underneath	☐	☒	☐	☐
11.	Supporting members	☐	☒	☐	☐
12.	General painting status	☐	☒	☐	☐
13.	Check of associated sling assembly if any	☐	☒	☐	☐
14.	Warning sign	☐	☒	☐	☐
Load Testing					
15.	Load test (as per the Mfg./LOLER) - SWL up to 10ton: PL = SWL x 2 10ton up to 160ton: PL = (1.04xSWL+9.6ton) - Over 160ton: PL = SWL x 1.1	☐	☒	☐	☐

S-Satisfactory, NS-Not Satisfactory, NA-Not Applicable, SE-Serviceable • Finding • Critical Finding

Finding:	Critical Finding:	Other Remarks:
Target Date of Closure:	Target Date of Closure:	

REPORT OF THOROUGH EXAMINATION LIFTING FRAME



Issued By:



Date of Issue: 21-04-2025

ReportNo.: **JO-10451/1**

ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe! ThinkSafe ThinkSafe! ThinkSafe!

PHOTOS OF INSPECTED LIFTING FRAME