

REPORT

OF THOROUGH EXAMINATION

MOBILE ELEVATING WORKING

PLATFORM

Date of Issue: 16-10-2025

ReportNo.: **JO-10951/A**

This equipment certificate complies with the requirements of Emirates International Accreditation Centre for inspection bodies working in the field of Lifting Equipment and Lifting Accessories (EIAC-RQ-IB-002), reference standard BS EN 280-1-2022, Manufacturer's Specification.

Owner Name: Mr Dhillon, Mr. Mani
Office Address: P.O. Box: 11072
Dubai
United Arab Emirates
Equipment Location: Gold 2, Silicon Oasis

INSPECTION DETAILS			
Date of Inspection:	16-10-2025	Expiry Date:	FAILED
Inspection Type:	THOROUGH		
Previous Inspection Report:	vh	Last Proof Load Test:	16-10-2025
Test Method	CSI-32	Calibrated Test Equipment:	gu
		Client Test Equipment:	hj
EQUIPMENT INFORMATION			
Equipment Description:	vh		
ID & Serial No.:	gu	Max. Base Unit Inclination:	ji
Model	ui	Maximum Lifting Height:	y
Equipment Type:	☐ Static Boom / Static Vertical ☒ Mobile Boom / Mobile vertical ☐ Push Around Vertical (PAV)	Overall Platform Dimensions:	n
Equipment Manufacturer:	h	SWL/No. of Person Allowed:	j
Registration No.:	h		
Production Year:	22-10-2025	Test Load Applied	bb
1. Is this the first examination after installation or assembly at a new location?		☒ Yes ☐ No	
2. If the answer to the above question is Yes, then has the equipment been installed correctly?		☒ Yes ☐ No	
3. Was the inspection carried out in accordance with an examination scheme?		☐ Yes ☒ No	

This is to certify that the above item/s described in this certificate was tested and particulars are correct.

CSSC has inventoried, inspected, verified and tested above mentioned equipment in accordance with the reference standards cited herein and consistent with CSSC policies and procedure. We certify this above mentioned equipment is **UNSAFE TO USE**, condition prevails at the time of this inspection.

All the information obtained /gathered during the inspection shall be preserved as confidential.

This inspection has been carried out as per local order no. : 2/2010;

This inspection certificate / report shall not be reproduced except in full without the approval of Claymore and the Client.

Inspected By: Katrina



Name & Signature of Inspector

REPORT

OF THOROUGH EXAMINATION MOBILE ELEVATING WORKING PLATFORM

Date of Issue: 16-10-2025

ReportNo.: **JO-10951/A**

EXAMINATION REPORT						
EQUIPMENT PARTS		S	NS	NA	SE	REMARKS
Documents and Equipment Verification:						
1.	Previous inspection report	☒	☐	☐	☐	
2.	Maintenance log sheet	☒	☐	☐	☐	
3.	Mfg. Manual & technical instruction	☒	☐	☐	☐	
4.	Operator license and Competency Certificate	☒	☐	☐	☐	
5.	NDT Certificate	☒	☐	☐	☐	
6.	Torque Report	☒	☐	☐	☐	
Ground control						
7.	Emergency stop	☒	☐	☐	☐	
8.	Engine	☒	☐	☐	☐	
9.	Electrical Wiring & Electrical Condition	☒	☐	☐	☐	
10.	Battery condition	☒	☐	☐	☐	
11.	Lever & operating control panel	☒	☐	☐	☐	
12.	Tires	☒	☐	☐	☐	
13.	Emergency Auxiliary device	☒	☐	☐	☐	
14.	Revolving Beacon	☒	☐	☐	☐	
15.	Lights Indication-Head, Brake, Reverse	☒	☐	☐	☐	
Components & Hydraulic system						
16.	Boom	☒	☐	☐	☐	
17.	Main Jib & Cylinder	☒	☐	☐	☐	
18.	Outer Jib & Cylinder	☒	☐	☐	☐	
19.	Scissor Arm Structure & Cylinder	☒	☐	☐	☐	
20.	Hydraulic oil level, tank, hose & fittings	☒	☐	☐	☐	
Basket control						
21.	Basket condition	☒	☐	☐	☐	
22.	Floor condition	☒	☐	☐	☐	
23.	Reverse Alarm Indication	☒	☐	☐	☐	
24.	Horn	☒	☐	☐	☐	
25.	Dead paddle condition	☒	☐	☐	☐	
26.	Lever & operating control panel	☒	☐	☐	☐	
27.	Base unit & Mechanical structure	☒	☐	☐	☐	
28.	Bolts & Nuts fittings condition	☒	☐	☐	☐	
29.	Alignment	☒	☐	☐	☐	
30.	Leveling	☒	☐	☐	☐	
31.	Inclination device	☒	☐	☐	☐	
Other accessories						
32.	Fire Extinguisher	☒	☐	☐	☐	
33.	Warning sign	☒	☐	☐	☐	
34.	Safety instruction	☒	☐	☐	☐	
Load test						
35.	Safe Working Load (100%)	☒	☐	☐	☐	
36.	Load Sensing System (RL x 120%)	☒	☐	☐	☐	
37.	Overload Test (Manual=150% / Powered=125%)	☒	☐	☐	☐	

S-Satisfactory, NS-Not Satisfactory, NA-Not Applicable, SE-Serviceable • Finding • Critical Finding

Finding:	Critical Finding:	Other Remarks:
Target Date of Closure:	Target Date of Closure:	

REPORT

OF THOROUGH EXAMINATION

MOBILE ELEVATING WORKING

PLATFORM



Issued By:



Date of Issue: 16-10-2025

ReportNo.: **JO-10951/A**

PHOTOS OF INSPECTED MEWP