

ISO/IEC 17020 IB-002

COMPANY WITH QUALITY SYSTEM CERTIFIED BY DNV GL = ISO 9001 =



Security & Safety Consultants

P. U. Box 23420, Dubai, U.AE, Tel.: +971 4 8848446, Fax: +971 4 8841242 E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

Job Order No : 10847			Purchase Order No : Mr. Ramu			CSSC Report No: 00001
Date of Inspection	Time Arrived	Time Left	Site Hou	ır Travel Hours	Total Time	Comment if required
27-05-2025	09:58:44	10:01:27	00:02:43	3	00:02:43	
Customer Data:						
Customer Name: VISTAWALL INTERNATIONAL Contact No: NA						
Company Name & Address: P.O. Box - 18040,						
Dubai,						
United Arab Emirates.						
Equipment Location: Jafza, Dubai						
Equipment Description:						
FORKLIFT 10847/1						
, 						
l						
Scope of Work:						
Virtual Test \square Functional Test \square Load Test \square Witness $oxdot M$ Verification $oxdot M$						
Document required:						
Inspector carry the ch	ecklist:	Yes□	No ☑	Inspection carr	y Test method:	Yes □ No 🗹
Inspection carry filled Risk assessment form: Yes ☑ No □						
Customer acceptance certificate:						
The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction.						
Travelling time, expense & mileage will be charged extra. Inspector Name: Maricris Barro Elcano Client Name: VISTAWALL INTERNATIONAL						
Inspector Name: Maricris Barro Elcano Client Name: VISTAWALL INTERNATIONAL						HUNAL

Sign & date: 27-05-2025

Sign & date: 27-05-2025