



ISO/IEC 17020

IB-002

COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV GL
= ISO 9001 =**Security & Safety Consultants**



P. O. Box 23420, Dubai, U.AE, Tel.: +971 4 8848446, Fax: +971 4 8841242
E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

Job Order No : 10878			Purchase Order No : 329/0084/POM			CSSC Report No : 00001
Date of Inspection	Time Arrived	Time Left	Site Hour	Travel Hours	Total Time	Comment if required
22-07-2025	15:42:41	15:42:58	00:00:17		00:00:17	

Customer Data:	
Customer Name: ASCON	Contact No: NA
Company Name & Address: P.O.Box 5238, Dubai, United Arab Emirates	
Equipment Location: Akoya	

Equipment Description:
CONSTRUCTION HOIST 10878/1 - Rejected test

Scope of Work:			
Virtual Test <input type="checkbox"/> Functional Test <input type="checkbox"/> Load Test <input type="checkbox"/> Witness <input type="checkbox"/> Verification <input checked="" type="checkbox"/>			
Document required:			
Inspector carry the checklist:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Inspection carry Test method:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Inspection carry filled Risk assessment form:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		
Customer acceptance certificate:			
The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction. Travelling time, expense & mileage will be charged extra.			
Inspector Name: Maricris Barro Elcano		Client Name: ASCON	
			
Sign & date: 22-07-2025		Sign & date: 22-07-2025	