

Job Order No: 10758

ISO/IEC 17020 IB-002

COMPANY WITH QUALITY SYSTEM CERTIFIED BY DNV GL = ISO 9001 =



CSSC Report No: 00001

Security & Safety Consultants

P. U. Box 23420, Dubai, U.AE, Tel.: +971 4 8848446, Fax: +971 4 8841242 E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

Purchase Order No: NA

Date of Inspection	Time Arrived	Time Left	Site Hour	Travel Hours	Total Time	Comment if required
12-05-2025	09:44:42	09:47:13	00:02:31		00:02:31	
Customer Data:						
Customer Name: FOURTH WALL DESIGN LLC Contact No: NA						
Company Name & Address: P.O.Box: 81896						
Dubai UAE						
Equipment Location: @ CSSC Training Room						
Equipment Description:						
CHAIN SLING 10758/1						
Scope of Work:						
Virtual Test □ Functional Test □ Load Test ☑ Witness □ Verification ☑						
Document required:						
Inspector carry the checklist:			☐ No 🗹	Inspection carry	y Test method:	Yes ☑ No □
Inspection carry filled Risk assessment form: Yes □ No ☑						
Customer acceptance certificate:						

The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction.

Sign & date: 12-05-2025

Sign & date: 12-05-2025

Client Name: FOURTH WALL DESIGN LLC

Travelling time, expense & mileage will be charged extra.

Inspector Name: Maricris Barro Elcano