

ISO/IEC 17020 IB-002

COMPANY WITH QUALITY SYSTEM CERTIFIED BY DNV GL = ISO 9001 =



Security & Safety Consultants

P. U. Box 23420, Dubai, U.AE, Tel.: +971 4 8848446, Fax: +971 4 8841242 E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

Job Order No : 10891			Purchase Order No : NA				CSSC Report No: 00001
Date of Inspection	Time Arrived	Time Left	Site Ho	ur	Travel Hours	Total Time	Comment if required
13-06-2025	10:08:27	10:09:53	00:01:2	26		00:01:26	
Customer Data:							
Customer Name: ACCURATE MEEZAN TRADING LLC Contact No: NA							
Company Name & Address: P.O.Box :40646							
Dubai							
U.A.E							
Equipment Location: NA							
Equipment Description:							
HOOK 10891/1							
Scope of Work:							
Virtual Test □ Functional Test □ Load Test □ Witness □ Verification ☑							
Document required:							
Inspector carry the ch			□ No 🗹		Inspection carry	/ Test method:	Yes ☑ No □
Inspection carry filled Risk assessment form: Yes ☑ No □							
Customer acceptance certificate:							
The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction. Travelling time, expense & mileage will be charged extra.							
Inspector Name: Maricris Barro Elcano				Client Name: ACCURATE MEEZAN TRADING LLC			

Sign & date: 13-06-2025

Sign & date: 13-06-2025