



ISO/IEC 17020
IB-002

COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV GL
= ISO 9001 =



Security & Safety Consultants

P. O. Box 23420, Dubai, U.A.E, Tel.: +971 4 8848446, Fax: +971 4 8841242
E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

Job Order No : 10601			Purchase Order No : LPO-VLPS-2014/152			CSSC Report No : 00001
Date of Inspection	Time Arrived	Time Left	Site Hour	Travel Hours	Total Time	Comment if required
30-04-2025	14:55:20	15:09:26	00:14:06		00:14:06	

Customer Data:

Customer Name: VALPAS SAFETY SERVICES

Contact No:

Company Name & Address: P. O. Box - 87832,
Dubai,
United Arab Emirates.

Equipment Location:

Equipment Description:

CHAIN SLING 10601/1
CHAIN SLING 10601/2
CHAIN SLING 10601/3
CHAIN SLING 10601/4
CHAIN SLING 10601/5
CHAIN SLING 10601/6
CHAIN SLING 10601/7
CHAIN SLING 10601/8
CHAIN SLING 10601/9
CHAIN SLING 10601/10

Scope of Work:

Virtual Test ☐ Functional Test ☐ Load Test ☐ Witness ☒ Verification ☐

Document required:

Inspector carry the checklist: Yes ☒ No ☐ Inspection carry Test method: Yes ☐ No ☒

Inspection carry filled Risk assessment form: Yes ☐ No ☒

Customer acceptance certificate:

The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction.
Travelling time, expense & mileage will be charged extra.

Inspector Name: Katrina

Client Name: VALPAS SAFETY SERVICES

happy



Sign & date: 30-04-2025

Sign & date: 30-04-2025