



ISO/IEC 17020
IB-002

COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV GL
= ISO 9001 =



Security & Safety Consultants

P. O. Box 23420, Dubai, U.A.E, Tel.: +971 4 8848446, Fax: +971 4 8841242
E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

| | | | | | | |
|----------------------|--------------|-----------|-----------------------------------|--------------|------------|------------------------|
| Job Order No : 10961 | | | Purchase Order No : 3241/0092/POM | | | CSSC Report No : 00001 |
| Date of Inspection | Time Arrived | Time Left | Site Hour | Travel Hours | Total Time | Comment if required |
| 16-10-2025 | 16:23:48 | 16:34:52 | 00:11:04 | | 00:11:04 | |

Customer Data:

Customer Name: ASCON

Contact No: NA

Company Name & Address: P.O.Box 5238,
Dubai,
United Arab Emirates

Equipment Location: Al Quoz

Equipment Description:

CHAIN SLING 10961/2 - Pending
CHAIN SLING 10961/4 - Pending
CHAIN SLING 10961/1 - Pending

Scope of Work:

Virtual Test ☐ Functional Test ☐ Load Test ☒ Witness ☐ Verification ☒

Document required:

| | | | |
|---|---|-------------------------------|---|
| Inspector carry the checklist: | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> | Inspection carry Test method: | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| Inspection carry filled Risk assessment form: | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> | | |

Customer acceptance certificate:

The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction.
Travelling time, expense & mileage will be charged extra.

Inspector Name: Maricris Barro Elcano

Client Name: ASCON

Sign & date: 16-10-2025

Sign & date: 16-10-2025