



ISO/IEC 17020
IB-002

COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV GL
= ISO 9001 =



Security & Safety Consultants



P. O. Box 23420, Dubai, U.AE, Tel.: +971 4 8848446, Fax: +971 4 8841242
E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

Job Order No : 11094			Purchase Order No : 237277/1			CSSC Report No : 00016
Date of Inspection	Time Arrived	Time Left	Site Hour	Travel Hours	Total Time	Comment if required
11-11-2025	16:26:26	17:38:51	01:12:25	02:00:00	03:12:25	

Customer Data:	
Customer Name: DAMEN SHIPYARDS SHARJAH FZE	Contact No: NA
Company Name & Address: P. O. Box - 52125, Hamriyah FZ, Sharjah, United Arab Emirates	
Equipment Location: Hamriyah Damen Yard	

Equipment Description:	
HOOK 11094/1 - Rejected	ggggg
HOOK 11094/2 - Pending	
HOOK 11094/3 - Rejected	1234
HOOK 11094/4 - Pending	
HOOK 11094/6 - Rejected	ppppppppp
EYEBOLT 11094/7 - Pending	

Scope of Work:			
Virtual Test <input checked="" type="checkbox"/> Functional Test <input checked="" type="checkbox"/> Load Test <input checked="" type="checkbox"/> Witness <input checked="" type="checkbox"/> Verification <input checked="" type="checkbox"/>			
Document required:			
Inspector carry the checklist:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Inspection carry Test method:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Inspection carry filled Risk assessment form:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		
Customer acceptance certificate:			
The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction. Travelling time, expense & mileage will be charged extra.			
Inspector Name: Katrina		Client Name: DAMEN SHIPYARDS SHARJAH FZE	
			
Sign & date: 11-11-2025		Sign & date: 11-11-2025	