



ISO/IEC 17020

IB-002

COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV GL
= ISO 9001 =

**Security & Safety Consultants**



P. O. Box 23420, Dubai, U.AE, Tel.: +971 4 8848446, Fax: +971 4 8841242
E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

Job Order No : 11042			Purchase Order No : 10054106			CSSC Report No : 00017
Date of Inspection	Time Arrived	Time Left	Site Hour	Travel Hours	Total Time	Comment if required
12-11-2025	00:27:47	02:22:14	01:54:27		01:54:27	

Customer Data:	
Customer Name: EMAAR PROPERTIES P.J.S.C	Contact No: NA
Company Name & Address: Emaar Square, Building No.3, United Arab Emirates PO Box No. 9440, Downtown Dubai	
Equipment Location: Al Arta Bldg	

Equipment Description:	
ELEVATOR 11042/1 - Pending	rejected nehaaa new
ELEVATOR 11042/3 - Pending	
ELEVATOR 11042/4 - Pending	

Scope of Work:			
Virtual Test <input type="checkbox"/> Functional Test <input type="checkbox"/> Load Test <input type="checkbox"/> Witness <input type="checkbox"/> Verification <input checked="" type="checkbox"/>			
Document required:			
Inspector carry the checklist:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Inspection carry Test method:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Inspection carry filled Risk assessment form:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		
Customer acceptance certificate:			
The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction. Travelling time, expense & mileage will be charged extra.			
Inspector Name: Katrina		Client Name: EMAAR PROPERTIES P.J.S.C	
			
Sign & date: 11-11-2025		Sign & date: 11-11-2025	