



ISO/IEC 17020
IB-002

COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV GL
= ISO 9001 =



Security & Safety Consultants



P. O. Box 23420, Dubai, U.A.E, Tel.: +971 4 8848446, Fax: +971 4 8841242
E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

Job Order No : 10714			Purchase Order No : 112213			CSSC Report No : 00001
Date of Inspection	Time Arrived	Time Left	Site Hour	Travel Hours	Total Time	Comment if required
08-05-2025	10:11:19	10:22:16	00:10:57	00:10:01	00:20:58	

Customer Data:	
Customer Name: DANWAY L.L.C.	Contact No: NA
Company Name & Address: P.O.Box : 50048 Dubai United Arab Emirates	
Equipment Location: NA	

Equipment Description:
OVERHEAD CRANE 10714/1
OVERHEAD CRANE 10714/2
OVERHEAD CRANE 10714/3

Scope of Work:			
Virtual Test <input type="checkbox"/> Functional Test <input type="checkbox"/> Load Test <input type="checkbox"/> Witness <input type="checkbox"/> Verification <input checked="" type="checkbox"/>			
Document required:			
Inspector carry the checklist:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Inspection carry Test method:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Inspection carry filled Risk assessment form:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		
Customer acceptance certificate:			
The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction. Travelling time, expense & mileage will be charged extra.			
Inspector Name: Wazeem Ibrahim		Client Name: DANWAY L.L.C.	
			
Sign & date: 08-05-2025		Sign & date: 08-05-2025	