



ISO/IEC 17020

IB-002

COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV GL
= ISO 9001 =**Security & Safety Consultants**



P. O. Box 23420, Dubai, U.AE, Tel.: +971 4 8848446, Fax: +971 4 8841242
E-mail: claysafe@emirates.net.ae www.claymoresafe.com

TESTING ENGINEERS REPORT & SITE TIME RECORD

Job Order No : 11043			Purchase Order No : 7050053723/NO PO for 01 Manli			CSSC Report No : 00024
Date of Inspection	Time Arrived	Time Left	Site Hour	Travel Hours	Total Time	Comment if required
13-11-2025	11:37:04	11:47:26	00:10:22		00:10:22	

Customer Data:	
Customer Name: BELLELI ENERGY S.P.A. FZE	Contact No: NA
Company Name & Address: P.O. Box 42322, Sharjah, United Arab Emirates	
Equipment Location: Hamreiyah	

Equipment Description:	
CHAIN SLING 11043/3 - Pending	fgy
CHAIN SLING 11043/4 - Pending	
CHAIN SLING 11043/5 - Pending	
CHAIN SLING 11043/6 - Pending	
CHAIN SLING 11043/7 - Pending	ghh
CHAIN SLING 11043/8 - Pending	
CHAIN SLING 11043/9 - Rejected	cvh
CHAIN SLING 11043/10 - Pending	

Scope of Work:	
Virtual Test <input type="checkbox"/> Functional Test <input type="checkbox"/> Load Test <input type="checkbox"/> Witness <input type="checkbox"/> Verification <input checked="" type="checkbox"/>	
Document required:	
Inspector carry the checklist:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Inspection carry filled Risk assessment form:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Customer acceptance certificate:	
The above work has been completed/progressed: I have read & confirm this report & time sheet & certify the work has been done to my satisfaction. Travelling time, expense & mileage will be charged extra.	
Inspector Name: Katrina  Sign & date: 13-11-2025	Client Name: BELLELI ENERGY S.P.A. FZE  Sign & date: 13-11-2025