



RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 27-02-2025	Time: 12:45 PM	Location: SHJ	Client: THEJU
Project Name: LACHU	Project No: 12345678		
✓ = OK		N/A = Not Applicable	
		D = Defect	

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
27-02-2025	27-02-2025	87	7 Kg	CO2	✓	N/A	N/A	N

Comments: YYTR

Inspector				Site In charge			
Name:	VINI11			Name:	Employee-8		
Designation:	Steel Fitter			Designation:	Accounts Manager		
Signature/Date:	27-02-2025		RAY No: Emp-40	Signature/Date:			RAY No: Emp-8

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

Ref No: FR-618	Version. No:	01	Issued Date :	08.09.2016	Page No:	Page 1 of 1
----------------	--------------	----	---------------	------------	----------	-------------