

## **RAY International Electrical Equipments Maintenance LLC**

## **RAY International Electrical Contracting LLC**

## **RAY International Power LLC**

FIRE EXTINGUISHER INSPECTION LOG									Abu Dhabi/ Dubai			
Date: 13	-11-2024	Time:	11:34 AM	Location:	kottayam				Client:	THEJU		
Project Name:	LACHU					Project No:	12345678					
<b>√</b> = OK	= OK N/A = Not Applicable										D = Defect	
·					<u> </u>			·		·		

Inspection	Inspection	Tag No.	Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
13-11-2024	30-11-2024	ywuiw	3 Kg	H2O	N/A	N/A	N/A	hajakkakaakka

Inspector			Site In charge	Site In charge					
Name:	VINI11		Name:	Employee-10					
Designation:					Designation:				
Signature/Date:		13-11-2024	RAY No:	Emp-10	Signature/Date:	4	13-11-2024	RAY No: Emp-10	

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

Ref No: FR-618	Version. No:	01 Issued Date :	08.09.2016	Page No:	Page 1 of 1	
----------------	--------------	------------------	------------	----------	-------------	--