RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG				Abu Dhabi/ Dubai
Date: 09-11-2024	**Time:** 10:45:00	**Location:** location added location added location added locatior		**Client:** client-295
Project Name: Project-295		**Project No:** Project-295		
√ = OK	**N/A = Not Applicable**			**D = Defect**

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
09-11-2024	11-09-2024	r	1 Kg	CO2	✓	N/A	N/A	gggg

Comments: location added location added location added location added location added location added location added location added location added location added location added location added location added locati

Inspector			**Site In charge**		
Name:	sijinauser		**Name:**	Employee-210	
Designation:			**Designation:**		
Signature/Date:		**RAY No:** Emp-210	**Signature/Date:**		**RAY No:** Emp-210

Condition / fault to be checked:
Cylinder: - Free from damage, Label clean and legible, Owner clearly identified
Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage
Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)
Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration
Safety Pin: - Secured from accidental displacement, Seal in place