



RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 08-10-2025

Time: 02:58 PM

Location: kannur

Client: client-369

Project Name: Project-369

Project No: Project-369


✓ = OK

N/A = Not Applicable

D = Defect

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
08-10-2025	08-10-2025	123	5 Kg	CO2	N/A	✓	N/A	wetj

Comments:

Inspector				Site In charge			
Name:	Snigda			Name:	Employee-20		
Designation:	Electrical Foreman			Designation:	Procurement Manager		
Signature/Date:	 08-10-2025		RAY No: Emp-234	Signature/Date:			RAY No: Emp-20

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

Ref No: FR-618

Version. No:

01

Issued Date :

08.09.2016

Page No:

Page 1 of 1