



RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC



FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 13-11-2024	Time: 11:19 PM	Location: payyambalam	Client: THEJU
Project Name: LACHU		Project No: 12345678	
✓ = OK		N/A = Not Applicable	
		D = Defect	

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
13-11-2024	13-11-2024	thu	29 Kg	H2O	N/A	N/A	N/A	2r5

Comments: cbnnhggnj

Inspector				Site In charge			
Name:	VINI11			Name:	Employee-31		
Designation:				Designation:			
Signature/Date:	 13-11-2024	RAY No:	Emp-31	Signature/Date:	 13-11-2024	RAY No:	Emp-31

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place