

RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG													Abu Dhabi/ Dubai		
Date: 21-11	I-2024	Time: 10:07 AM			Location: ee					Client:	THEJU				
Project Name: LACHU Project No: 12345678									'8						
√ = OK	v = OK N/A = Not Applicable										D = Defect				
Date of Inspection	Due date		Extinguisher Tag No.	Volume o			Contents		Pressure Gauge	Hoses		Safety Pin		Remarks / Signature	
21-11-2024	-2024 21-11-202		w3rf	58 Kg		CO2			N/A N			N/A	dfg	dfgv	
Comments: jjsnsmsmdmsmsksjsjdjjdjdjshshehehehennsbshsbsbsbsbsbsbsbsbsbsbsbsbsbsbsbsbsb															
Inspector								Site In charge							
Name:	VINI11							ı	Name:	Employee-9					
Designation:									Designation:						
Signature/Date:	0			21-11-2024	RAY I	No:	Emp-9		Signature/Date:		•			RAY No: Emp-9	

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

	ersion. No:	Issued Date :	08.09.2016	Page No:	Page 1 of 1	
--	-------------	---------------	------------	----------	-------------	--