



RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC


FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 13-11-2024	Time: 06:56 PM	Location: kochi	Client: client-319
Project Name: Project-319		Project No: Project-319	
✓ = OK		N/A = Not Applicable	
		D = Defect	

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
08-11-2024	20-11-2024	3	2 Kg	DCP	✓	N/A	N/A	sfa

Comments: hjjhlo

Inspector				Site In charge			
Name:	testuser			Name:	Employee-43		
Designation:	Helper			Designation:	Assistant Jointer		
Signature/Date:	 13-11-2024	RAY No:	Emp-284	Signature/Date:		RAY No:	Emp-43

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place