

## **RAY International Electrical Equipments Maintenance LLC**

## **RAY International Electrical Contracting LLC**

## **RAY International Power LLC**

FIRE EXTINGUIS	Abu Dhabi/ Dubai			
Date: 13-11-2024 Time: 05:02 PM	Location: kannur	Client: client-187		
Project Name: Project-187	Project No: Project-187			
<b>√</b> = OK	D = Defect			

Date of	Due date of	Extinguisher	Volume of the	Contents	Pressure		Safety	Remarks /
Inspection	Inspection	Tag No.	Cylinder		Gauge	Hoses	Pin	Signature
13-11-2024	14-11-2024	1	3 Kg	CO2	✓	✓	✓	ааааааа

Inspector			Site In charge			
Name:	Admin	Name:	Employee-2			
Designation:		Designation:				
Signature/Date:	13-11-2024	RAY No: Emp-2	Signature/Date:	13-11-2024	RAY No: Emp-2	

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

Ref No: FR-618	Version. No:	01	Issued Date :	08.09.2016	Page No:	Page 1 of 1
----------------	--------------	----	---------------	------------	----------	-------------