RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 21-11-2024	**Time:** 10:07 AM	**Location:** ee	**Client:** client-188
Project Name: Project-188		**Project No:** Project-188	

√ = OK **N/A = Not Applicable** **D = Defect**

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
21-11-2024	21-11-2024	w3rf	58 Kg	CO2	N/A	N/A	N/A	dfgv

Comments: jjsnsmsmdmsmsksjsjdjjdjdjjdhshshehehehennsbshsbsbsbssbbshshsbsbddbhdhsbebsbsbsbshshsbbsbssbebeebebebebebehehhebebeshbssnsnshhssb bsbshehehehhehehehehehehehehehhehehehhwbwbssnsnnsbhehehehehhehebebebhshene

Inspector			**Site In charge**		
Name:	VINI11		**Name:**	Employee-9	
Designation:			**Designation:**		
Signature/Date:	21-11-2024	**RAY No:** Emp-9	**Signature/Date:**		**RAY No:** Emp-9

Condition / fault to be checked:
Cylinder: - Free from damage, Label clean and legible, Owner clearly identified
Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage
Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)
Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration
Safety Pin: - Secured from accidental displacement, Seal in place