

RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG									Abu Dhabi/ Dubai			
Date : 09-11-2024 Time : 10:45 AM				Lo	Location: location added location added location added location				Client:	ient: client-295		
Project Name: Project-295 Project No: Project-295												
√ = O K					N/A = Not Applicable				D = Defect			
Date of Inspection	Due date date d		Extinguisher Tag No.	Volume of to		Contents		Pressure Gauge	Hoses		Safety Pin	Remarks / Signature
09-11-2024	11-09-202	24	r	1 Kg		CO2		✓	N/A		N/A	9999

		location added							
Comments:	location added location added locati								

Inspector				Site In charge				
Name:	sijinauser			Name:	Employee-210			
Designation:				Designation:				
Signature/Date:	09-11-2024	RAY No:	Emp-210	Signature/Date:	09-11-2024	RAY No: Emp-210		

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

Ref No: FR-618	Version. No:	01 Issued Date :	08.09.2016	Page No:	Page 1 of 1	
----------------	--------------	------------------	------------	----------	-------------	--