

## **RAY International Electrical Equipments Maintenance LLC**

## **RAY International Electrical Contracting LLC**

## **RAY International Power LLC**

FIRE EXTINGUISHER INSPECTION LOG												Abu Dhabi/ Dubai		
Date: 15-11-2024 Time: 12:17 PM					Location: nn					Client:	client-188			
Project Name:	88			No: Project-1	88									
V = OK N/A = Not Applicable								D = Defect						
Date of Inspection	Due date Inspection		Extinguisher Tag No.	Volume of Cylinde		Contents		Pressure Gauge	Hoses		Safety Pin	Remarks / Signature		
15-11-2024	15-11-20	24	hj	3 Kg		H2O		N/A	N/A		N/A	bnnn		
Commonter	-	-	isjdjjdjdjjdhshsheh nehehehehehhe						sbssbebeebeb	ebebebeh	ehhebebeshbs	snsnshhssb		
Inspector								Site In charge						
Name:	VINI11							Name:	Employee-8					
Designation:	esignation:							Designation:						
Signature/Date:	2			15-11-2024	RAY No:	: Emp-8	9	Signature/Date:				RAY No: Emp-8		

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

Ref No: FR-618	Version. No:	01	Issued Date :	08.09.2016	Page No:	Page 1 of 1
----------------	--------------	----	---------------	------------	----------	-------------