



RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

### FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 18-08-2025

Time: 10:21 AM

Location: knr

Client: client-2

Project Name: Project-2

Project No: Project-2


V = OK

N/A = Not Applicable

D = Defect

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
18-08-2025	18-08-2025	q	1 Kg	CO2	N/A	✓	N/A	test1
18-08-2025	18-08-2025	q	1 Kg	CO2	N/A	N/A	N/A	123

Comments: test

Inspector				Site In charge			
Name:	VINI11			Name:	Employee-21		
Designation:	Steel Fitter			Designation:	Health & Safety Engineer		
Signature/Date:	 18-08-2025		RAY No: Emp-40	Signature/Date:			RAY No: Emp-21

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

Ref No: FR-618

Version. No:

01

Issued Date :

08.09.2016

Page No:

Page 1 of 1