

RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG							Abu Dhabi/ Dubai							
Date: 14-11	-2024	Time:	12:54 AM	ı	Location:	lc)				Client:	client-187		
Project Name: Project-187					Project I	No: Project-187								
V = OK N/A = Not Applicable				D = Defect					t					
Date of Inspection	Due date		Extinguisher Tag No.	Volume of Cylinde			Contents		Pressure Gauge	Hoses		Safety Pin		Remarks / Signature
14-11-2024	16-11-2024		hhkjh	4 Kg		DCP			N/A	N/A		N/A	ghhj	

Inspector			Site In charge				
Name:	abc		Name:	Employee-8			
Designation:			Designation:				
Signature/Date:	14-11-2024	RAY No: Emp-8	Signature/Date:		RAY No: Emp-8		

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

Ref No: FR-618 Version. No: 01 Issued Date: 08.09.2016 Page No: Page 1 of 1
