



RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 13-05-2025	Time: 11:59 AM	Location: kn	Client: client-247
Project Name: Project-247		Project No: Project-247	
✓ = OK		N/A = Not Applicable	
		D = Defect	

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
13-05-2025	13-05-2025	q	1 Kg	CO2	N/A	N/A	N/A	qwe

Comments:

Inspector				Site In charge			
Name:	VINI11			Name:	Employee-16		
Designation:	Steel Fitter			Designation:	Mechanical Engineer		
Signature/Date:	 13-05-2025	RAY No:	Emp-40	Signature/Date:		RAY No:	Emp-16

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place