



RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 18-11-2024

Time: 09:18 AM

Location: Dubai

Client: client-210

Project Name: Project-210

Project No: Project-210


✓ = OK

N/A = Not Applicable

D = Defect

| Date of Inspection | Due date of Inspection | Extinguisher Tag No. | Volume of the Cylinder | Contents | Pressure Gauge | Hoses | Safety Pin | Remarks / Signature |
|--------------------|------------------------|----------------------|------------------------|----------|----------------|-------|------------|---------------------|
| 18-11-2024 | 18-11-2024 | FE 02 | 4 Kg | CO2 | ✓ | ✓ | ✓ | good condition |

Comments: 3rd party certificate to be obtained

| Inspector | | | | Site In charge | | | |
|-----------------|-----------------------------------------------------------------------------------|------------|----------------|-----------------|-------------|--|----------------|
| Name: | test | | | Name: | Employee-19 | | |
| Designation: | | | | Designation: | | | |
| Signature/Date: |  | 18-11-2024 | RAY No: Emp-19 | Signature/Date: | | | RAY No: Emp-19 |

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place

Ref No: FR-618

Version. No:

01

Issued Date :

08.09.2016

Page No:

Page 1 of 1