


		RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC	
LIFTING GEARS INSPECTION checklist123		Abu Dhabi/ Dubai	
Date: 19-06-2023	Location: d	Client rhidyzi	
Project Code: 123	Project Details: 3r		
Sl. No Of LiftingGear: cvhedit	Detail Of LiftingGear: 123		

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
1	Does all Lifting Tackles covered by valid third party inspection?			✓	
2	Lifting Gear Current Colour code?		✓		
3	Is the SWL displayed?		✓		
4	Does all the lifting gears stored properly?	✓			
5	In case of nylon/web slings, does protection from sharp edges exist?		✓		
6	Are hook & safety latch & wire rope in good condition?		✓		
7	Are all lifting tackles in good condition?	✓			
Personnel					
8	Is the In-charge of lifting gears aware about the storing of lifting gears?	✓			
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?	✓			
10	Are all personnel involved in lifting appropriately trained?	✓			
Comments : fgghjffxy					

Inspected By: treesaSang	Site In charge: Fahad Iqbal
Sign/Date: 	Sign/Date:
RAY No: 23-06-00012	RAY No: 23-06-00012