

RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC

	LIFTING GEAR	S INSPECT		Abu Dhabi/ Dubai		
Date:	07-08-2023	Location:	knr		Client: client 1	
Project Code:	SangProject1		Project Details: sang p	rojec	it	
SI. No O LiftingG		-	Detail Of h LiftingGear:			

	ITEMS	СОМ	PLIAN	CE				
SI. No	ITEMS	YES	NO	NA	REMARKS			
Equipment								
2	Lifting Gear Current Colour code?	~						
3	Is the SWL displayed?	✓						
4	Does all the lifting gears stored properly?		√					
5	In case of nylon/web slings, does protection from sharp edges exist?		√					
6	Are hook & safety latch & wire rope in good condition?		√					
7	Are all lifting tackles in good condition?		✓					
1	Does all lifting tackles covered by valid third party inspection?	~						
	Personnel							
8	Is the In-charge of lifting gears aware about the storing of lifting gears?	✓						
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?	~						
10	Are all personnel involved in lifting appropriately trained?	~						
Comments	: hhh jkkkkk	•	•	•				

jkkkkk hhhbb vhhhh bshbh mjhgu vfghu bhhjkf bhgff vghhh bcxff

Ref No:	FR-608	Version. No	01	Issued Date :	08.09.2016	Page No:	1	
---------	--------	-------------	----	---------------	------------	----------	---	--

SI. No	ITEMS	YES NO NA	REMARKS
Inspected By:	Sijina	Site In charge: sijina-	test
Sign/Date:			
RAY No:	RU/603	RAY No:	603

Signature: