
	RAY International Electrical Contracting & Maintenance LLC
	RAY International Electrical Contracting LLC
	RAY International Power LLC

LIFTING GEARS INSPECTION CHECKLIST		Abu Dhabi/ Dubai
Date: 30-08-2023	Location: dph	Client: No Client
Project Code: SangProject1	Project Details: sang project(description)	
Sl. No Of LiftingGear: h	Detail Of LiftingGear: g	

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
2	Lifting Gear Current Colour code?	✓			
3	Is the SWL displayed?		✓		
4	Does all the lifting gears stored properly?		✓		
5	In case of nylon/web slings, does protection from sharp edges exist?	✓			
6	Are hook & safety latch & wire rope in good condition?		✓		
7	Are all lifting tackles in good condition?		✓		
Personnel					
8	Is the In-charge of lifting gears aware about the storing of lifting gears?	✓			
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?	✓			
10	Are all personnel involved in lifting appropriately trained?		✓		
Comments : hgn					

Inspected By: Sijina	Site In charge: sijina-test
Sign/Date: 	
RAY No: RU/603	RAY No: RU/603

Signature: