



RAY International Electrical Contracting & Maintenance LLC
RAY International Electrical Contracting LLC
RAY International Power LLC

LIFTING GEARS INSPECTION CHECKLIST

Abu Dhabi/ Dubai

Date: 15-02-2024

Location: uaq

Client:

Project Code: RU/712/20/PRJ

Project Details: RU/712/20/PRJ

Sl. No Of LiftingGear: ddsf

Detail Of LiftingGear: dg

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
1	Does all Lifting Tackles covered by valid third party inspection?		✓		
2	Lifting Gear Current Colour code?			✓	
3	Is the SWL displayed?	✓			
4	Does all the lifting gears stored properly?		✓		
5	In case of nylon/web slings, does protection from sharp edges exist?			✓	
6	Are hook & safety latch & wire rope in good condition?				
7	Are all lifting tackles in good condition?				
Personnel					
8	Is the In-charge of lifting gears aware about the storing of lifting gears?			✓	
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?			✓	
10	Are all personnel involved in lifting appropriately trained?		✓		
Comments : dfd					

Inspected By: Reacttest	Site In charge: Sudheer Thirumalmel Kalarickal
Sign/Date:	
RAY No: RU/022	RAY No: RU/022

Signature: