



RAY International Electrical Contracting & Maintenance LLC
RAY International Electrical Contracting LLC
RAY International Power LLC

LIFTING GEARS INSPECTION CHECKLIST

Abu Dhabi/ Dubai

Date: 10-08-2023

Location: Dh

Client: No Client


Project Code: SangProject1

Project Details: sang project(description)

Sl. No Of LiftingGear: g

Detail Of LiftingGear: a

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
1	Does all lifting tackles covered by valid third party inspection?	✓			
2	Lifting Gear Current Colour code?		✓		
3	Is the SWL displayed?	✓			
4	Does all the lifting gears stored properly?		✓		
5	In case of nylon/web slings, does protection from sharp edges exist?	✓			
6	Are hook & safety latch & wire rope in good condition?	✓			
7	Are all lifting tackles in good condition?	✓			
Personnel					
8	Is the In-charge of lifting gears aware about the storing of lifting gears?	✓			
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?		✓		
10	Are all personnel involved in lifting appropriately trained?		✓		
Comments : a					

Inspected By: Sijina	Site In charge: Ahmed Eid al Habshi Al Badri
Sign/Date: 	
RAY No: RU/010	RAY No: RU/010

Signature: