

	RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC		
---	--	--	--

LIFTING GEARS INSPECTION checklist		Abu Dhabi/ Dubai	
Date: 13-06-2023	Location: d	Client ghh	
Project Code: RU/1010/22/PRJ		Project Details: RU/1010/22/PRJ	
Sl. No Of Lifting fg	Detail Of Lifting fgh		

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
1	Does all Lifting Tackles covered by valid third party inspection?			✓	
2	Lifting Gear Current Colour code?			✓	
3	Is the SWL displayed?	✓			
4	Does all the lifting gears stored properly?			✓	
5	In case of nylon/web slings, does protection from sharp edges exist?			✓	
6	Are hook & safety latch & wire rope in good condition?	✓			
7	Are all lifting tackles in good condition?			✓	
Comments : vhhh					

Inspected By: Gokul Singh	Site In charge Saleh Said Mattar Al Azizi
Sign/Date: 21-06-2023	Sign/Date:
RAY No: 23-06-00006	RAY No: 23-06-00006