

## RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC

LIFTING GEAR	S INSPECTION CHECKLIST	Abu Dhabi/ Dubai			
<b>Date:</b> 11-11-2024	Location: uuyuuh	Client: client-188			
Project Project-188  Code:	Project Details: Project-188				
SI. No Of ttfg LiftingGear:	Detail Of gf LiftingGear:				

	I ITEMS		PLIAN	CE		
SI. No			NO	NA	REMARKS	
	Equipment					
1	Does all lifting tackles covered by valid third party inspection?	~				
2	Lifting Gear Current Colour code?	<b>✓</b>				
3	Is the SWL displayed?	<b>*</b>			jjsnsmsmdmsmsksjsjdjjdjdjjdhshshe hehehennsbshsbsbsbsbsbsbsbsbsbsbeb ddbhdhsbebsbsbsbsbsbshshsbbsbsbeb eebebebebehehhebebeshbssnsn shhssbbsbshehehehheheheheheheheheheheheh	
4	Does all the lifting gears stored properly?	<b>✓</b>				
5	In case of nylon/web slings, does protection from sharp edges exist?	<b>✓</b>				
6	Are hook & safety latch & wire rope in good condition?	<b>✓</b>				
7	Are all lifting tackles in good condition?	<b>✓</b>				
	Personnel	•				
8	Is the In-charge of lifting gears aware about the storing of lifting gears?	<b>✓</b>				
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?	<b>✓</b>				
10	Are all personnel involved in lifting appropriately trained?	<b>✓</b>				

## Comments:

Ref No:	FR-608	Version. No	01	Issued Date :	08.09.2016	Page No:	1	
---------	--------	-------------	----	---------------	------------	----------	---	--

SI. No		ITEMS	COMPLIAN YES NO	NA	REMARKS
Inspected By	r: Admin		Site In charge:	Empl	oyee-9
Sign/Date:			•		
RAY No:	Emp-9		RAY No:	Em	p-9

Signature: