

	RAY International Electrical Contracting & Maintenance LLC
	RAY International Electrical Contracting LLC
	RAY International Power LLC

LIFTING GEARS INSPECTION CHECKLIST		Abu Dhabi/ Dubai
Date: 22-11-2024	Location: ffffgg	Client: client-247
Project Code: Project-247	Project Details: Project-247	
Sl. No Of LiftingGear: 666tttt	Detail Of LiftingGear: ffgvgv	

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
1	Does all lifting tackles covered by valid third party inspection?	✓			
2	Lifting Gear Current Colour code?	✓			bhbhhhhjhjh
3	Is the SWL displayed?	✓			
4	Does all the lifting gears stored properly?	✓			
5	In case of nylon/web slings, does protection from sharp edges exist?	✓			
6	Are hook & safety latch & wire rope in good condition?	✓			
7	Are all lifting tackles in good condition?	✓			
Personnel					
8	Is the In-charge of lifting gears aware about the storing of lifting gears?	✓			
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?	✓			
10	Are all personnel involved in lifting appropriately trained?	✓			
Comments : ggg					

Inspected By: abc	Site In charge: Employee-9
Sign/Date:	
RAY No: Emp-9	RAY No: Emp-9

Signature: