



RAY International Electrical Contracting & Maintenance LLC
RAY International Electrical Contracting LLC
RAY International Power LLC

LIFTING GEARS INSPECTION CHECKLIST

Abu Dhabi/ Dubai

Date: 08-04-2025

Location: knr

Client: client-283

Project Code: Project-283

Project Details: Project-283

Sl. No Of LiftingGear: f

Detail Of LiftingGear: d

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
1	Does all lifting tackles covered by valid third party inspection?		✓		
2	Lifting Gear Current Colour code?		✓		
3	Is the SWL displayed?		✓		
4	Does all the lifting gears stored properly?		✓		
5	In case of nylon/web slings, does protection from sharp edges exist?		✓		
6	Are hook & safety latch & wire rope in good condition?		✓		
7	Are all lifting tackles in good condition?		✓		
Personnel					
8	Is the In-charge of lifting gears aware about the storing of lifting gears?		✓		
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?		✓		
10	Are all personnel involved in lifting appropriately trained?		✓		
Comments : ewq					

Inspected By: VINI11	Site In charge: Employee-9
Sign/Date: 	
RAY No: Emp-9	RAY No: Emp-9

Signature:

Ref No: FR-608	Version. No 01	Issued Date : 08.09.2016	Page No: 1
-----------------------	-----------------------	---------------------------------	-------------------