



RAY International Electrical Contracting & Maintenance LLC
RAY International Electrical Contracting LLC
RAY International Power LLC

LIFTING GEARS INSPECTION CHECKLIST

Abu Dhabi/ Dubai

Date: 07-08-2023

Location: knr

Client: client 1

Project Code: SangProject1

Project Details: sang project

Sl. No Of LiftingGear: h

Detail Of LiftingGear: h

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
2	Lifting Gear Current Colour code?	✓			
3	Is the SWL displayed?	✓			
4	Does all the lifting gears stored properly?		✓		
5	In case of nylon/web slings, does protection from sharp edges exist?		✓		
6	Are hook & safety latch & wire rope in good condition?		✓		
7	Are all lifting tackles in good condition?		✓		
1	Does all lifting tackles covered by valid third party inspection?	✓			
Personnel					
8	Is the In-charge of lifting gears aware about the storing of lifting gears?	✓			
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?	✓			
10	Are all personnel involved in lifting appropriately trained?	✓			

Comments : hhh
jkkkkkk
hhhbb
vhhhh
bshbh
mjhgu
vfghu
bhhjfkf
bhgff
vghhh
bcxff

Ref No: FR-608

Version. No

01

Issued Date :

08.09.2016

Page No:

1

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	

Inspected By:	Sijina	Site In charge:	sijina-test
Sign/Date:			
RAY No:	RU/603	RAY No:	RU/603

Signature: