



RAY International Electrical Contracting & Maintenance LLC
RAY International Electrical Contracting LLC
RAY International Power LLC

LIFTING GEARS INSPECTION CHECKLIST

Abu Dhabi/ Dubai

Date: 14-08-2023

Location: Dh

Client: No Client


Project Code: SangProject1

Project Details: sang project(description)

Sl. No Of LiftingGear: h

Detail Of LiftingGear: h

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
1	Does all lifting tackles covered by valid third party inspection?	✓			
2	Lifting Gear Current Colour code?	✓			
3	Is the SWL displayed?		✓		
4	Does all the lifting gears stored properly?	✓			
5	In case of nylon/web slings, does protection from sharp edges exist?	✓			
6	Are hook & safety latch & wire rope in good condition?	✓			
7	Are all lifting tackles in good condition?	✓			
Personnel					
8	Is the In-charge of lifting gears aware about the storing of lifting gears?	✓			
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?	✓			
10	Are all personnel involved in lifting appropriately trained?		✓		
Comments : ghn					

Inspected By: Sijina	Site In charge: sijina-test
Sign/Date: 	
RAY No: RU/603	RAY No: RU/603

Signature: